

DP-THC conversion table

DP-TH & DP-IAQ part numbers	DP-THC part numbers	Description
DPWT011000	DPWS100000	Indoor sensor with NTC temperature output
DPWT010000	DPWS210000	Indoor sensor - temperature - humidity with 0-10 V or 4-20 mA analogue output
DPWC110000		
DPWC112000		
DPWC111000	DPWS310000	Indoor sensor - NTC temperature - humidity with 0-10 V or 4-20 mA analogue output
DPWC115000		
Model not available	DPWS410000	Indoor sensor - temperature - humidity - CO2 with 0-10 V or 4-20 mA analogue output
Model not available	DPWS420000	Indoor sensor - temperature - humidity - CO2 with 0-10 V or 4-20 mA analogue output and display
DPWC114000	DPWS510000	Indoor sensor - temperature - humidity with RS485 serial output
DPWC1140G0		
DPWT014000		
DPWQ60B010 (*)		
DPWQ61B010 (*)	DPWS520000	Indoor sensor - temperature - humidity with RS485 serial output and display
DPWQ70B010 (*)	DPWS610000	Indoor sensor - temperature - humidity - CO2 with RS485 serial output
DPWQ71B010 (*)	DPWS620000	Indoor sensor - temperature - humidity - CO2 with RS485 serial output and display
DPUT011000	DPUS100000	Outdoor sensor - NTC temperature - humidity with 0-10 V or 4-20 mA analogue output
DPPT011000		
DPPT010000	DPUS210000	Outdoor sensor - temperature - humidity with 0-10 V or 4-20 mA analogue output
DPPC110000		
DPUC110000		
DPPC210000		
DPPC112000		
DPPC212000		
DPPC111000	DPUS310000	Outdoor sensor - NTC temperature - humidity with 0-10 V or 4-20 mA analogue output
DPPT014000	DPUS510000	Outdoor sensor - temperature - humidity with RS485 serial output
DPPC114000		
DPPC214000		
DPDT011000	DPDS100000	Duct sensor - temperature with NTC output
DPDT010000	DPDS210000	Duct sensor - temperature - humidity with 0-10 V or 4-20 mA analogue output
DPDC110000		
DPDC210000		
DPDC112000		
DPDC212000		
DPDC111000	DPDS310000	Duct sensor - NTC temperature - humidity with 0-10 V or 4-20 mA analogue output
Model not available	DPDS410000	Duct sensor - temperature - humidity - CO2 with 0-10 V or 4-20 mA analogue output
DPDT014000	DPDS510000	Duct sensor - temperature - humidity with RS485 serial output
DPDC114000		
DPDC214000		
DPDQ60B010 (*)		
DPDQ70B010 (*)	DPDS610000	Duct sensor - temperature - humidity - CO2 with RS485 serial output
Model not available	DPRS510000	Compact sensor - temperature - humidity with RS485 serial output - 3 m cable
DPRC11A000	DPRS710000	Compact sensor - NTC Temperature - humidity 0-5 V analogue output - 3 m cable
DPRC13A000		

(*) Model not in phase-out